

## **Asbestos Management Policy**

A **Full Asbestos Report** was carried out on 23/6/17 and a copy is kept by the Nursery in the **Building Compliance and Safety Certificates and Reports** folder.

- Asbestos has been identified in a number of places in the halls and kitchen.
- The Asbestos Report will be shared with any contractors carrying out works in the nursery buildings, and a signature requested to show that the contractor has taken responsibility for reading the report. Please see Contractors Policy.
- Contractors will be asked to stop working and inform the management immediately if they suspect they may have discovered or disturbed asbestos containing material.
- If asbestos is suspected then the area will be evacuated immediately and isolated by closing all doors and windows, and advice sought from a licensed contractor. Anyone who may have been contaminated by asbestos containing material should be isolated and decontaminated as quickly as possible, with clothing treated as contaminated waste.