

Asbestos Management Policy

At Wood St Nursery we understand it is the duty of the responsible person to find out if asbestos is present in the nursery and that it is appropriately managed, as required by the **Control of Asbestos Regulations 2021**. A **Full Asbestos Report** was carried out on 23/6/17, and an Asbestos Management Report for Wood St Nursery was carried out on 31/5/2019. Copies are kept by the Nursery in the **Building Compliance and Safety Certificates and Reports** folder.

- Asbestos has been identified and managed in the large hall and interconnecting and kitchen lobby to the small hall and also under the eaves of the large hall in the garden. Asbestos has been removed from the cellar.
- The Asbestos Report will be shared with any contractors carrying out works in the nursery buildings, and a signature requested to show that the contractor has taken responsibility for reading the report. Please see Contractors Policy.
- Contractors will be asked to stop working and inform the management immediately if they suspect they may have discovered or disturbed asbestos containing material.
- If asbestos is suspected then the area will be evacuated immediately and isolated by closing all doors and windows, and advice sought from a licensed contractor. Anyone who may have been contaminated by asbestos containing material should be isolated and decontaminated as quickly as possible, with clothing treated as contaminated waste.

Updated 28.11.2024